



Case Study: Bristol George Square Development

Client

King Sturge Management.

Problem

The underside of the central atrium at the development needed leak detection and sealing as water ingress was causing problems in the office space below.

Solution

Rope Task's riggers installed WPN (Work Position Nets) to the problem areas beneath the central atrium, using the existing steel structure as supports. Safety ropes were then installed which allowed rope access technicians to gain access to the WPN's and carryout leak detection and water sealing works.



Rope Task Limited
Hillside House
5 Brunswick Terrace
Wednesbury WS10 9DA
West Midlands

Tel: 0121 556 2958
Fax: 0121 502 4266
Email: admin@ropetask.com
Web: www.ropetask.com