



Rope Task Limited
Hillside House
5 Brunswick Terrace
Wednesbury WS10 9DA
West Midlands

Tel: 0121 556 2958
Fax: 0121 502 4266
Email: admin@ropetask.com
Web: www.ropetask.com

Case Study: The Mailbox, Birmingham

Client

Mailbox Management Limited

Problem

The exterior building maintenance cradle had become trapped on the monorail system above pedestrian walkway alongside the Mailbox complex. Without the use of cranes and MEWP's they had no way of retrieving the cradle.

Solution

Rope Task technicians carried out the following tasks using rope access techniques, without the use of cranes or MEWP's:

Gained access to the cradle monorail system using specialist access techniques. Using rigging techniques, lifted the cradle of the monorail system and safely lowered the cradle down to the floor so that repairs could take place, saving hundreds of pounds in hire costs for cranes or MEWP's.

